

Work Order ID 86095

86095

Page 1

Item ID: D3021-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Item Name: Tube Assembly

Stop *NS2*

Start Date: 20/06/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 04/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: *MLJ*

Date: *12/06/20* Tooling:

Run Start *NR1*

QC:

Date: SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3021	Rev A								
100		0.00							
100	Large Fab								
Large Fab	Memo	0.00							
Large Fab	1-Cut tube as per Dwg D3021								
	2-Drill tube as per Dwg D3021 using D8622								
	3-Deburr								
	4-Weld as per Dwg D3021 QSI004								
	A/R 4130 Rod Batch: <i>M118825</i>								
110	QC9- Inspect visual per QSI004- Fusion Welds	0.00							
110									
QC	Memo	0.00							
Quality Control									

0

12-7-12

10

26/07/09

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 86095

June-20-12 2:48:11 PM

86095

Page 2

Item ID: D3021-041
Revision ID:
Item Name: Tube Assembly

Accept

N900040100

Setup Start ***NS1***
Stop ***NS2***

Start Date: 20/06/2012 Start Qty: 1.00 ***1***
Required Date: 04/07/2012 Req'd Qty: 1.00 ***1***

Cust Item ID:
Customer:

Reference:

Approvals: Process Plan: Date: Tooling: Date: Run Start ***NR1***
QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120 QC5- Inspect part completeness to step on W/O

0.00

120

QC

Memo

0.00

Quality Control

130 Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

0.00

130

Powdercoat

Powder Coating

Memo

START TIME: 11:00

OVEN TEMPERATURE: 320°F

FINISH TIME: 11:30

0.00

140

QC3- Inspect Part Finish

0.00

140

QC

Memo

0.00

Quality Control

Handwritten notes:
IX ✓ M-L 12/07/10
1 ✓ BK 12-7-10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 86095

June-20-12 2:48:11 PM

86095

Page 3

Item ID: D3021-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Tube Assembly

Start Date: 20/06/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 04/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursTool ID Tool # Plan
Code Accept Reject Reject Insp.
Qty Qty Number Stamp

150

Identify as per dwg & Stock Location: GA

0.00

150

Packaging

Memo

0.00

Packaging

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.00

Quality Control

MLJ 12/07/10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

June-20-12 2:48:14 PM

Page 1

Work Order ID: 86095

86095

Parent Item: D3021-041

D3021-041

Parent Item Name: Tube Assembly

Start Date: 20/06/2012

Required Date: 04/07/2012

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP 01.10.23 New Issue SM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3017-11		Manufactured	No			100	Each	50.0000	2	2			

D3017-11

cap

**

EL 12-7-12-

Location

WA021

76851

Loc Qty

50

50

Loc Code

2-

M4130NT0.750W.049

Purchased

No

100

f

105.9200

2.0833

2.192947

M4130NT0 750W 049

4130 RD Tube .750 x.049W

**

EL 12-7-12

Location

MAT033

120350

121025

Loc Qty

105.92

65.61

40.31

Loc Code

2-19

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN CP	DRAWN BY CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3021	REV. A SHEET 1 OF 1
DATE 01.05.18		TITLE TUBE ASSEMBLY	SCALE 1:4
A	01.05.18	NEW ISSUE	

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 810025 MCJ
12/06/20



D3021-041 TUBE ASSEMBLY
(D3021-1 TUBE)

NOTES:

- 1) PART IS SYMMETRIC ABOUT CENTERLINE
- 2) MATERIAL: AISI 4130 TUBE, $\phi 0.75$ DIA x 0.049 WALL (M4130N-T0750W049)
- 3) WELD PER DART QSI 004
- 4) FINISH: POWDER COAT GREY SANDTEX (REF 4.3.5.6) PER DART QSI 005 4.3
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

RELEASED
01.05.30

Copyright © 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries